

M series HMI symbols with V300

Device



PLC: M511s

HMI: V300 software.


Process

PLC part:


1. Generate the HMI symbols:



2. Select HMI model then check




3. Generate the HMI symbol table(Here we use the Modbus_TCP), then save the csv file.




HMI part


1. Device information




2. Load HMI symbol file



3. Then select the generated file.



4. If the previous tag is not delete, you will see the import file as:



5. Create a numeric input:

